



Build a Better Planet



Overview of Corrective Measures Study (CMS) Recommendations for Boeing Areas

The Boeing Company
Santa Susana Field Laboratory

Key Messages

■ Recent progress includes:

- Comprehensive evaluations in progress using RFI data to make Corrective Measure Study (CMS) recommendations in Boeing areas
- Evaluations and draft CMS recommendations completed for Boeing RFI Subarea 5/9 South

■ What did we find?

- Interim CMS areas are recommended based on soil and groundwater locations that exceed screening levels
- Final recommended CMS areas will be based on risk assessment and modeling results, and included in RFI reports to be approved by DTSC
- Following cleanup, the areas where corrective measures are implemented will be safe for the future intended use
- Areas outside the recommended CMS areas (including properties adjacent to SSFL) are already safe for current and future intended use

■ What are the next steps?

- Submit CMS recommendations for Subarea 5/9 South in draft RFI report for DTSC review
- Complete evaluations, make CMS recommendations, and submit draft RFI reports to DTSC for remaining Boeing Subareas (1A Central, 5/9 North, and 10 currently in progress)



Thank you