



The Boeing Company  
Santa Susana Field Laboratory  
5800 Woolsey Canyon Road  
Canoga Park, CA 91304-1148

Via FedEx

April 29, 2013

In reply refer to SHEA-113439

Mr. Ray Leclerc  
SSFL Project Director  
Calif. Environmental Protection Agency  
Dept. of Toxic Substance Control  
1001 "I" Street  
P.O. Box 806  
Sacramento, CA 95812-0806



Dear Mr. Leclerc:

Subject: Submittal of Former Building 4015 Post-Demolition Summary Report Boeing Santa Susana Field Laboratory, Ventura County, California

At the request of the Department of Toxic Substance Control (DTSC), the Boeing Company (Boeing) provides this post-demolition summary report with information that describes the demolition debris results and subsurface observations (if any) after demolition completion of the former Building 4015, located within Administrative Area IV.

Providing this post-demolition summary report is consistent with the request made by the DTSC within the February 11, 2010 memorandum, "DTSC Comments on Draft Standard Operating Procedures for Building Demolition Debris Characterization and Management".

Demolition/removals were performed using the Boeing protocols established in the Standard Operating Procedures (SOP): Building Demolition and Debris Characterization and Management for the Santa Susana Field Laboratory (Boeing, 2010) and Standard Operating Procedures, Boeing Demolition Debris Characterization and Management, Amendment 1 that applies to non-radiological Boeing-owned buildings in Area IV dated November 01, 2012.

This post-demolition summary report consists of the following attachments:

- Attachment A – Post-demolition maps and photographic documentation
- Attachment B – Demolition Field Summary
- Attachment C – Radiological Release Survey and Waste Certification
- Attachment D – Demolition debris – Waste sample results and manifests
- Attachment E – Demolition debris – Recycled invoices



April 29, 2013

Page 2

SHEA-113439

If you have any questions, please call Art Lenox at (818) 466-8795 or Steve Fischer at (562) 209-4998.

Respectfully,

A handwritten signature in black ink, appearing to read 'Art Lenox', written over a light blue horizontal line.

Art Lenox,  
Project Manager  
Environmental Remediation

A handwritten signature in black ink, appearing to read 'Steve Fischer', written over a light blue horizontal line.

Steve Fischer  
Demolition Project Manager

Enclosure: B/4015 post-demolition summary report

cc: Mr. Paul Carpenter, DTSC  
Mr. Mark Malinowski, DTSC  
Mr. John Jones, DOE  
Ms. Jill Benson, CH2MHILL  
Ms. Dixie Hambrick, MWH